

BELZONA REPAIRS ASH SCREW CONVEYOR BEARINGS

ID: 690


Industry: General Industry
Application: MPT-Mechanical Power Transmission

Customer Location: Cement Works, Usje, Macedonia
Application Date: September 2004

Substrate: Steel
Products: * Belzona® 1131 (Bearing Metal),

Problem

Severe wear due to dusty working environment.



Photograph Descriptions

- * Application situation ,
- * Worn friction bearing ,
- * Repaired bearings ,
- * Finished application ,

Application Situation

Friction Bearings on Ash Screw Conveyor

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-9.

Belzona Facts

The bearings were made of grey iron and were lasting just 3-4 weeks. Following the application of Belzona® 1131 the bearings were lasting 3-4 months thus saving down time as the bearings needed replacing less often.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve