

BELZONA WEATHERPROOFS AIRPORT FIRE STATION ROOF

ID: 696

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Concrete*
Products: ** Belzona® 3131 (WG Membrane) ,*

Customer Location: *Airport, UK*
Application Date: *May 2003*

Problem

This fire station roof was leaking and the local airport authority wanted to repair it and extend its life, rather than a full replacement.



Photograph Descriptions

* 1. Roof to be coated
2. The roof after cleaning and surface preparation
3. Coated roof
4. Completed application ,

Application Situation

Airport fire station roof

Application Method

Application was carried out in accordance with Belzona® System Leaflet RPA-1

Belzona Facts

The unusual construction of this roof posed a problem for other roofing systems. Belzona was chosen as the solution, as the alternative was to completely replace the roof. 2 years on and the application is still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve