

BELZONA REPAIRS HOLED VALVE HOUSING

ID: 699

Industry: *Buildings & Structures*
Application: *CEP-Centrifugal Pumps*
Substrate: *Grey Cast Iron*
Products: ** Belzona® 1311 (Ceramic R-Metal) ,*
** Belzona® 1341 (Supermetalgilde) ,*

Customer Location: *Petrochemical Plant, Macedonia*
Application Date: *May 2001*

Problem

Cavitation had caused the valve housing to become holed



Photograph Descriptions

- * Holed valve housing. ,
- * Metal plates used to reinforce the exterior. ,
- * Rebuilt housing. ,
- * Completed application. ,

Application Situation

Valve Housing

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-8.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

The plant did not have a reserve valve in there warehouse and a new replacement would take weeks to be delivered. Belzona solved the problem in just two days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

