

BELZONA SEALS INSULATOR LEAKS

ID: 702

Industry: Power
Application: GSS-Gaskets, Seals and Shims
Substrate: Porcelain and Aluminum
Products: * Belzona® 2121 (D&A Hi-Coat Elastomer) ,

Customer Location: Power Plant, British Columbia, Canada
Application Date: August 2003

Problem

Seal within insulators eroded and as a result oil leakage began to occur.



Photograph Descriptions

* Surface preparation in progress Surface preparation by grit blasting completed Completed application. ,

Application Situation

Power Line Insulators

Application Method

Application carried out in accordance with Belzona Know-How Leaflet GSS-3.

Belzona Facts

Belzona products have been used for many of these types of sealing applications with tremendous success.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve