

BELZONA SEALS SF6 LEAKS AT HYDROELECTRIC POWER STATION

ID: 705

Industry: Power

Customer Location: Hydroelectric Power Plant, British Columbia, Canada

Application: GSS-Gaskets, Seals and Shims


Application Date: 1993

Substrate: Steel

Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,

Problem

SF6 gas was leaking from the joints of the system requiring regular refilling.



Photograph Descriptions

- * Belzona® 2211 was injected into the gap between the 2 flanges. ,
- * Application shown in #1 completed. ,
- * Another flange sealed. ,

Application Situation

SF6 gas pipe

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet GSS-4.

Belzona Facts

This application has been in service for many years with only minor repairs required. TOTAL TIME IN SERVICE - 13 YEARS.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve