

# BELZONA HELPS SWEET MANUFACTURER AGAIN AFTER 8 YEARS

ID: 737

Industry: General Industry  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Steel & Belzona® 1321  
Products: \* Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Sweet Manufacturer, Belgium  
Application Date: September 2005

## Problem

The Belzona coating, applied 8 years previously, was still in good condition and had only suffered some discolouration. The client, however, wanted to apply a fresh coat of Belzona.



## Photograph Descriptions

- \* 8-year-old Belzona® 1321 coating ,
- \* Another view of 8-year-old Belzona® 1321 coating ,
- \* New Belzona® 1321 coating ,
- \* Coated hatch ,

## Application Situation

Mixing tank

## Application Method

The Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

The client was so pleased that the original Belzona coating lasted 8 years that they once again contacted Belzona to re-coat the machine.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve