

# BELZONA MANWAY OPENING

ID: 74

Industry: Chemical & Petrochemical  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Stainless Steel  
Products: \* Belzona® 1111 (Super Metal) ,

Customer Location: Petroleum Refinery in Texas  
Application Date: 1991

## Problem

Opening on chemical tank was corroded to the point where a good seal was not possible.



## Photograph Descriptions

- \* Surface preparation performed with the repair area taped off. ,
- \* Manway rebuilt. ,

## Application Situation

Manway opening on chemical storage tank.

## Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-10.

## Belzona Facts

For only \$128 in Belzona® 1111 (Super Metal), downtime and expensive welding was averted. The repair has held for many years, and is still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve