

BELZONA KEEPS THE TANK AFLOAT!

ID: 7494

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon Steel
Products: * Belzona 1391T,

Customer Location: Offshore oil production platform, Gabon
Application Date: March 2017

Problem

The original coating had failed in most areas. Pitting on the bottom head and on the shell manway was of particular concern.



Photograph Descriptions

- * 1. View of the tank ,
- * 2. First coat application completed on the shell ,
- * 3. Second coat application in progress ,
- * 4- Second coat application completed on the inner part of the tank ,

Application Situation

Floatation tank operating at 90C, in contact with produced water.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

Belzona 1391T has been selected for its corrosion resistance in an immersed environment at high temperatures, offering long term protection for the oil operator.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve