

PROTECTING HVAC DUCTWORK WITH BELZONA


ID: 7534

Industry: Heating, Ventilation & Air Conditioning
Application: VPF-Valves, Pipes and Fittings
Substrate: Various insulation materials
Products: * Belzona 3211 (Lagseal) ,

Customer Location: France
Application Date: 2003

Problem

Solution required to seal and protect weathered ductwork insulation.



Photograph Descriptions

* 1. Damaged insulation 2. Close up of the damage 3. Belzona repair after 14 years in service 4. Belzona repair after 14 years in service ,

Application Situation

Insulated heating and ventilation ductwork on a university roof.

Application Method

Application was carried out in accordance with Belzona System Leaflet VPF-12.

Belzona Facts

Belzona 3211 offers outstanding protection from the elements, including UV exposure. It is micro-porous and will prevent liquid from penetrating through it while allowing any moisture to evaporate, so maintaining thermal efficiency and reducing CUI. This application was photographed in 2017, after 14 years in service. Still in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve