

# ROOF OF AN ART DECO BUILDING SAVED WITH BELZONA

ID: 7550

**Industry:** Buildings & Structures  
**Application:** RPA-Roof Problem Areas  
**Substrate:** Bitumen felt  
**Products:** \* Belzona 3111 (Flexible Membrane) ,

**Customer Location:** Lancashire, England, UK  
**Application Date:** 2016

## Problem

The roof is a large expanse with several separate roof areas on different levels. There were numerous leak areas through the existing roofing felt that required repair to prevent permanent damage to the wonderful interior which is still used for numerous events on a regular basis including ball room dancing.



## Photograph Descriptions

- \* 1. Overview of the building ,
- \* 2. One small section of the roof before ,
- \* 3. The same small section after application of Belzona 3111 ,
- \* 4. Belzona 3111 coated section close to the dome area ,

## Application Situation

Large bitumen felted flat roof on a beautiful Art Deco Public Building.

## Application Method

The application was carried out in accordance with Belzona System Leaflets RPA-1,6,8 & 10

## Belzona Facts

This was a very large area with lots of upstands and gutter detail situated in a very aggressive environment right next to the coast with strong winds, sea, salt and sand constantly attacking the building. The client required a product that was capable of dealing with all the complex roof detail and all that the elements could throw at it whilst at the same time proving them with long term value for money. Belzona could tick all these boxes.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve