

Belzona saves a cement silo lid

ID: 7555

Industry: General Industry

Customer Location: Concrete products manufacturer,
Bedfordshire, UK

Application: TCC-Tanks and Chemical Containment
Areas

Application Date: August 2017

Substrate: Steel chequer plate

Products: * Belzona 1111 (Supermetal) ,
* Belzona 5811 (Immersion Grade) ,

Problem

Any moisture ingress will ruin the stored materials. The customer had noticed problems and after inspecting found that the lid was severely corroded and was letting in rainwater. The silo is 11 metres high, to replace the lid would be logistically very difficult and incredibly expensive.



Photograph Descriptions

- * 1. The silo lid at the start of the repairs ,
- * 2. A closer look at the damage ,
- * 3. The lid repaired with Belzona 1111 plate bonding techniques ,
- * 4. The finished lid after application of Belzona 5811 ,

Application Situation

The customer manufactures concrete beams, blocks and other structures at their large site in Bedfordshire. The cement silo is a vital part of their plant

Application Method

Application was carried out in accordance with Belzona System Leaflets TCC-1 and TCC-5. Steel plates were bonded to the lid using B1111 where required to repair the holed areas before applying two coats of Belzona 5811 to provide overall corrosion protection.

Belzona Facts

Having the silo lid refurbished rather than replaced saved the company in excess of £21000 for a new lid and the contractor fees. In addition, the Belzona solution allowed them to carry on production as the silo could still be used safely whilst work was being

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

carried out saving a huge amount of money in lost time and revenue.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

