

Belzona Keeps The Cover On Annealing Oven

ID: 7566

Industry: *Steel & Metal Processing*

Application: *ENC-Engines and Casings*

Substrate: *Iron*

Products: ** Belzona 1121 (Super XL-Metal) ,*

Customer Location: *Metallurgy Company, Slovakia*

Application Date: *2011*

Problem

The cover had distorted and did not sit correctly on the base and caused a CO2 leakage.



Photograph Descriptions

- * 1. Annealing ovens ,
- * 2. Surface preparation ,
- * 3. Belzona 1121 application ,
- * 4. Cover replaced ,

Application Situation

Large annealing oven at a metal manufacturing plant.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 7.

Belzona Facts

Using the Belzona solution allowed the original equipment to be used as a former, ensuring a perfect fit. Rebuilding in this way also meant the line was back up sooner than expected.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve