

Belzona Repairs a Car Engine Casing


ID: 7567

Industry: *Transport*
Application: *ENC-Engines and Casings*
Substrate: *Iron*
Products: ** Belzona 1111 (Super Metal) ,*

Customer Location: *Civil Society, Slovakia*
Application Date: *2016*

Problem

The freezing winter temperatures had caused excessive movement and a crack in the engine casing.



Photograph Descriptions

- * 1. Cracked engine. ,
- * 2. Crack detection. ,
- * 3. Surface preparation. ,
- * 4. Belzona 1111 application with reinforcement tape. ,

Application Situation

Cracked Engine Casing on a government vehicle.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet ENC - 1.

Belzona Facts

Welding this kind of damage would take a lot of time and money. Rebuilding with Belzona 1111 was a faster and more economical solution for the customer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve