# **BELZONA PROTECTS MIXING TANK**

ID: 757

Industry: Water / Wastewater Customer Location: Dairy in Oklahoma, USA

Application: TCC-Tanks and Chemical Containment Application Date: March, 2006

Areas

Substrate: Concrete

Products: \* Belzona® 5811 (Immersion Grade),

\* Belzona® 4111 (Magma Quartz),

#### **Problem**

Customer needed protection on their KMnO4 (Potassium Permanganate) mixing tank.









## **Photograph Descriptions**

- \* Bare unprotected mixing tank. ,
- \* Surface prepared and holes patched with Belzona® 4111. ,
- \* First coat Belzona® 5811 being applied. ,
- \* Final coat Belzona® 5811 applied.,

### **Application Situation**

During expansion, the large dairy constructed a new water plant to treat their own water (average 400,000 GPD).

### **Application Method**

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet TCC-15.

### **Belzona Facts**

Customer choose Belzona based on success of previous applications.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®

www.belzona.com