

BELZONA REPAIRS BROKEN RBC BASE

ID: 758

Industry: Water / Wastewater

Customer Location: Waste Water Treatment Plant in Oklahoma

Application: TCC-Tanks and Chemical Containment Areas

Application Date: February, 2006

Substrate: Concrete

Products: Belzona® 4111 (Magma Quartz)

Problem

While replacing the gearbox the customer broke the concrete base and anchors.



Photograph Descriptions

* Broken base , * Area prepared & conditioned, backboard in place, anchors aligned, and filling with Belzona® 4111 , * Base filled with Belzona® 4111. , * Completed repair back in operation. ,

Application Situation

Concrete base for gearbox on the RBC (Rotating Biological Collector).

Application Method

Application carried out in accordance with Belzona Know-How System Leaflet TCC-9.

Belzona Facts

The customer consulted with Belzona based upon previous successes. Traditional repair would have taken over a month with unacceptable downtime, and cost thousands of dollars. The Belzona repair was completed in a day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025