

Slide assembly with Belzona repair

ID: 7606

Industry: *Steel & Metal Processing*
Application: *ENC-Engines and Casings*
Substrate: *Steel*
Products: ** Belzona 1311 ,*

Customer Location: *Slovakia, metallurgic producer*
Application Date: *2014*

Problem

Corrosion accelerated due to the inclusion of water and chemicals within the process



Photograph Descriptions

- * 1. Damaged slide assembly ,
- * 2. Belzona 1311 application ,
- * 3. All surface were sanded down ,
- * 4. Support ready to work ,

Application Situation

Slide assembly were damaged from corrosion.

Application Method

Application was carried out in accordance with modified Belzona Know-How System Leaflet ENC 7.

Belzona Facts

Belzona was chosen because welding takes very long time with risk of the compromising the structural integrity.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve