

# Belzona refurbishes Brake test rollers

ID: 7609

Industry: *Transport*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Vehicle testing station, Slovakia*  
Application Date: *2016*

Substrate: *Steel*  
Products: *\* Belzona 1821 (Fluid Metal) ,*

## Problem

*After many thousand tests the surface of the rollers required a new non-slip surface applying.*



## Photograph Descriptions

- \* 1. Damaged rollers ,
- \* 2. Belzona 9211 Supergrip Aggregate application into Belzona 1821 ,
- \* 3. Ready to work ,

## Application Situation

Brake test rollers at vehicle testing station.

## Application Method

Application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-12.

## Belzona Facts

Customer needed quick repair in good quality and Belzona grip system has a proven track record for this application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve