

Belzona refurbishes Brake test rollers

ID: 7609

Industry: *Transport*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Vehicle testing station, Slovakia*
Application Date: *2016*

Substrate: *Steel*
Products: ** Belzona 1821 (Fluid Metal) ,*

Problem

After many thousand tests the surface of the rollers required a new non-slip surface applying.



Photograph Descriptions

- * 1. Damaged rollers ,
- * 2. Belzona 9211 Supergrip Aggregate application into Belzona 1821 ,
- * 3. Ready to work ,

Application Situation

Brake test rollers at vehicle testing station.

Application Method

Application was carried out in accordance with modified Belzona Know-How System Leaflet SHM-12.

Belzona Facts

Customer needed quick repair in good quality and Belzona grip system has a proven track record for this application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve