

# Cyclone coating protection with Belzona

ID: 7611

Industry: *Food & Drink*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Slovakia, starch factory*

Application Date: *2011*

Substrate: *Steel*

Products: *\* Belzona 1812 (Ceramic Carbide FP) ,*

## Problem

*Damaged cyclone*



## Photograph Descriptions

- \* 1. Ready for repair ,
- \* 2. Belzona 1812 application ,
- \* 3. Belzona 1812 application detail ,

## Application Situation

Milled corn material suffers and also adheres on the cyclone surface.

## Application Method

Application was carried out in accordance with modified Belzona System Leaflet SHM- 13

## Belzona Facts

Conventional welding to be out of service too long and also it is not long lasting solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve