

# Belzona repairs joints in concrete


ID: 7615

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona 4111 (Magma Quartz) ,  
\* Belzona 2211 (MP Hi-Build Elastomer) ,

**Customer Location:** Furniture production plant, Slovakia,  
**Application Date:** 2015

## Problem

Heavy fork lift truck traffic destroyed joint nosings.



## Photograph Descriptions

- \* 1. Damaged dilatation joint ,
- \* 2. Repair in progress ,
- \* 3. Belzona 2211 application ,
- \* 4. Joints ready for work ,

## Application Situation

dilatation (contraction) joints in concrete floor.

## Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-5 and FPA-6.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Customer tried to repair damaged joints several times with another product but after 2 weeks problem returned. After Belzona repair customer has no problem.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

