

Belzona repairs joints in concrete



ID: 7615

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 2211 (MP Hi-Build Elastomer) ,

Customer Location: Furniture production plant, Slovakia,
Application Date: 2015

Problem

Heavy fork lift truck traffic destroyed joint nosings.



Photograph Descriptions

- * 1. Damaged dilatation joint ,
- * 2. Repair in progress ,
- * 3. Belzona 2211 application ,
- * 4. Joints ready for work ,

Application Situation

dilatation (contraction) joints in concrete floor.

Application Method

Application was carried out in accordance with Belzona System Leaflet FPA-5 and FPA-6.

Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Customer tried to repair damaged joints several times with another product but after 2 weeks problem returned. After Belzona repair customer has no problem.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

