

Chemical canalization entry repaired with Belzona

ID: 7617

Industry: Chemical & Petrochemical
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete / Steel
Products: * Belzona 4131 (Magma-Screed) ,
* Belzona 5811 (Immersion Grade) ,

Customer Location: Petrochemical company, Slovakia
Application Date: 2016

Problem

Corrosion of the steel frame and damage to the concrete



Photograph Descriptions

- * 1. Chemical canalization entry. ,
- * 2. Belzona Conditioner application ,
- * 3. Belzona 4131 application ,
- * 4. Belzona 5811 in 2 layers ,

Application Situation

The concrete was destroyed from chemicals.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 9

Belzona Facts

Main benefit for the customer was time, because all repair was carried in very short time, but also important is resistant again chemicals.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025