

# Large storage tank protected with Belzona

ID: 7618

Industry: *Chemical & Petrochemical*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Steel*  
Products: *\* Belzona 5811 (Immersion Grade) ,  
\* Belzona 1111 (Super Metal) ,*

Customer Location: *Petrochemical company, Slovakia*  
Application Date: *2015*

## Problem

*The tank had been in service for twenty years and was suffering extensive corrosion damage*



## Photograph Descriptions

- \* 1. Tank after 20 years. ,
- \* 2. Blasting of the basin ,
- \* 3. Visible damages after blasting ,
- \* 4. Belzona 5811 coating applied in 2 layers ,

## Application Situation

Crude oil storage tank

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3 & TCC-5

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

## Belzona Facts

Customer needed quick and quality repair. All protection was realized with Belzona 5811. Deep corrosion was rebuilt with Belzona 1111.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

