

Belzona Allows Oil Tanker To Sail

ID: 7629

Industry: Marine
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon Steel
Products: * Belzona 1221 (Super E-Metal) ,
* Belzona 1161 (Super UW-Metal) ,

Customer Location: Taranto, Italy
Application Date: November 2017

Problem

Caused by internal corrosion, the pipe had multiple areas of low metal thickness.



Photograph Descriptions

- * 1. Initial situation ,
- * 2. Belzona 1221 and plate to fix the leak ,
- * 3. Surface Preparation ,
- * 4. Application completed ,

Application Situation

Corroded sea water inlet pipe under the floating line, inside the engine room of an oil tanker. It was not possible to restore/replace the pipe in drydock. In this condition inspector did not give permission to sail.

Application Method

The application was carried out in accordance with Belzona System Leaflet VPF-11. Following mechanical preparation a small plate was bonded with rapid cure Belzona 1221, then completed with a wrap of the pipe with Belzona 1161.

Belzona Facts

The Belzona application made it possible to repair and to secure the piping in one day, allowing the tanker to sail and avoiding downtime and more expensive activities in drydock.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve