

4311 COATS A SULFURIC ACID TANK AT A CHEMICAL PLANT

ID: 7648

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon steel.
Products: * Belzona 4311 (Magma CR1) ,

Customer Location: Northern Florida
Application Date: October 2017

Problem

Chemical attach onto the metal was taking a toll. The area was hard to shut down due to the need for this product during production.



Photograph Descriptions

- * 1. This is the tank after blasting with Black Beauty to get the required Belzona cleanliness standard. ,
- * 2. This shows the pump they used. ,
- * 3. The spray team about to start. ,
- * 4. Finished application of 4311. ,

Application Situation

The customer wanted to coat a previously uncoated Sulfuric Acid tank.

Application Method

The contractor used a heated plural component pump to do the application as per Belzona's spray instructions. The application was done in accordance to Belzona system leaflet TCC-5.

Belzona Facts

The Engineer had used Belzona at another plant and wanted to use Belzona for this application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

