

# NEW BELZONA COATING FOR TWO SIDE-BY-SIDE CONDENSER TANKS

ID: 7657

Industry: General Industry  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Steel  
Products: \* Belzona 5892 ,

Customer Location: Florida, USA  
Application Date: October 2017

## Problem

*The existing coating in the tanks was having some problems with delamination. The owner wanted them to be coated with Belzona. These tanks held water around 198 F. They had no agitation.*



## Photograph Descriptions

- \* 1. Two condenser tanks, side by side. ,
- \* 2. Blasting the tanks using Sponge Jet. ,
- \* 3 & 4. Newly re-coated tanks with two coats of Belzona 5892. ,

## Application Situation

Two condenser tanks.

## Application Method

The tanks were both blasted using the Sponge Jet method to control dust. Then two coats of Belzona 5892 were applied by hand using a brush and following the Manufacturer's Instructions for Use. The application was done in accordance with Belzona System Leaflet TCC-5.

## Belzona Facts

The Customer is well familiar with Belzona and likes to use it on their equipment. They have had good luck with Belzona in the past.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

*Copyright © Belzona International Limited 2025*

