

BELZONA SEALS COOLER SHELL

ID: 767

Industry: *Military*
Application: *HEX-Heat Exchangers*
Substrate: *Carbon Steel*
Products: *Belzona® 1111 (Super Metal)*

Customer Location: *Italian Navy*
Application Date: *October 2005*

Problem

Erosion corrosion had caused hole in the shell of the cooler. Location and timescale made replacement impossible.



Photograph Descriptions

* Cooler before repair , * Application underway , * Completing the application , * Close up of the repair ,

Application Situation

Main engine cooler

Application Method

Application was carried out in accordance with Belzona System Leaflet HEX-5.

Belzona Facts

Due to short period in port Belzona was only way to carry out the repairs on the warship with the cooler in place.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025