

Belzona Granogrip System Provides Safety at a Medical Facility

ID: 7670

Industry:

Application: FPA-Floor Problem Areas

Substrate: Steel

Products: * Belzona 4411 (Granogrip) ,
* Belzona 9211 (Supergrip Aggregate) ,

Customer Location: Medical Facility, Washington, USA

Application Date: November, 2017

Problem

Determining that the open grates would be a safety hazard and untreated steel would be a slip hazard the engineers called Belzona for a solution. Samples were sent to the building inspector and he chose Belzona 4411 GranoGrip with Belzona 9211 Aggregate.



Photograph Descriptions

- * 1. Open grate - safety hazard. ,
- * 2. Twelve steel plates after being grit blasted in a machine shop. ,
- * 3. & 4. Sidewalk drain covers in place. ,

Application Situation

New construction of a medical facility. The plans called for open grates over the sidewalk drains. The building inspector rejected the open grates as a safety hazard, especially for high heel shoes.

Application Method

The 12 - 1' x 3' plates were grit blasted in the shop. Belzona 4411 was brush applied and Belzona 9211 pressed in over the whole surface.

Belzona Facts

Belzona has assisted the medical facility in providing patients and visitors with a safe entry that visually meets the high standards of the development.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve