

# Belzona Granogrip System Provides Safety at a Medical Facility

ID: 7670

## Industry:

Application: FPA-Floor Problem Areas

Substrate: Steel

Products: \* Belzona 4411 (Granogrip) ,  
\* Belzona 9211 (Supergrip Aggregate) ,

Customer Location: Medical Facility, Washington, USA

Application Date: November, 2017

## Problem

Determining that the open grates would be a safety hazard and untreated steel would be a slip hazard the engineers called Belzona for a solution. Samples were sent to the building inspector and he chose Belzona 4411 GranoGrip with Belzona 9211 Aggregate.



## Photograph Descriptions

- \* 1. Open grate - safety hazard. ,
- \* 2. Twelve steel plates after being grit blasted in a machine shop. ,
- \* 3. & 4. Sidewalk drain covers in place. ,

## Application Situation

New construction of a medical facility. The plans called for open grates over the sidewalk drains. The building inspector rejected the open grates as a safety hazard, especially for high heel shoes.

## Application Method

The 12 - 1' x 3' plates were grit blasted in the shop. Belzona 4411 was brush applied and Belzona 9211 pressed in over the whole surface.

## Belzona Facts

Belzona has assisted the medical facility in providing patients and visitors with a safe entry that visually meets the high standards of the development.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve