

Belzona Keeps US Navy Fire Pump Ready to Run

ID: 7675

Industry: Marine
Application: CEP-Centrifugal Pumps
Substrate: Brass
Products: * Belzona 1111 (Super Metal) ,
* Belzona 1341 (Supermetalglide) ,

Customer Location: Washington, USA
Application Date: February 2017

Problem

Due to lack of frequent use, this fire pump onboard a US Navy ship sits for extended amounts of time with sea water inside of it causing severe corrosion. This makes the fire pump potentially unreliable in case of an emergency.



Photograph Descriptions

- * 1. Original condition of the impeller. ,
- * 2. Belzona 1111 applied to rebuild the damage. First coat of Belzona 1341 applied ,
- * 3. Belzona 1111 rebuilding the wear rings. ,
- * 4. Completed application, ready for re-assembly. ,

Application Situation

Fire pump impeller on-board a US Navy ship.

Application Method

Grit blasted to achieve a 3-5 mil profile, and coated with Belzona 1111 to fill in and rebuild the pitting and damage to a smooth clean finish. Allowed to firm up, and then overcoated with the first coat of Belzona 1341. The impeller wear ring was also heavily corroded and was machined down to a rough thread pattern and overbuilt with Belzona 1111 at this time. While waiting for the wear ring application to solidify, the second coat of Belzona 1341 was applied. Finally, the wear ring surface was machined back to the original specifications.

Belzona Facts

This impeller would have had to be replaced, but with Belzona materials being used, repairing it only cost a couple hundred US

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

dollars without risking heat distortion by welding on it. The added bonus is an increase in efficiency whenever the pump is operated.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

