

# BELZONA REFURBISHES ENTRANCE STEPS OUTSIDE A MUNICIPAL BUILDING

ID: 7683

## Industry:

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: \* Belzona 4111 (Magma Quartz) ,  
\* Belzona 5231 (SG Laminate) ,  
\* Belzona 9232 (Aggregate) ,  
\* Belzona 5233 ,

Customer Location: BC, Canada

Application Date: May 2017

## Problem

The entrance steps were looking "tired" and needed to be repaired and re-coated.



## Photograph Descriptions

- \* 1. The original coating removed ,
- \* 2. A full coat of Belzona 5231 (SG Laminate) in light grey applied to the prepared surface, saturated with Belzona 9232 (Lt Grey Quartz Aggregate) and over-coated with Belzona 5233. ,
- \* 3. All stair tread edges were highlighted with safety yellow. ,
- \* 4. Close up of completed stair surface. ,

## Application Situation

Entrance steps

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1. The original coating was removed using a Vacu-Grinder and the damaged areas rebuilt with Belzona® 4111 (Magma Quartz). A full coat of Belzona® 5231 (SG Laminate) (Lt Grey) was applied to the prepared surface and saturated with Belzona® 9232 (Lt Grey Quartz Aggregate) and over-coated with Belzona 5233 in Grey. All stair tread edges were highlighted with safety yellow.

## Belzona Facts

This municipality trusted Belzona based on the previous successes.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve