

# Belzona Composite Ferry Wrap


ID: 7698

Industry: *Transport*  
Application: *VPF-Valves, Pipes and Fittings*  
Substrate: *Mild Steel*  
Products: *\* Belzona 1121 (Super XL-Metal) ,*  
*\* Belzona 5821 ,*

Customer Location: *France*  
Application Date: *November 2017*

## Problem

*Suffering from external corrosion*



## Photograph Descriptions

- \* 1. Damaged pipe ,
- \* 2. Belzona 1121 wrap in progress ,
- \* 3. Composite Wrap complete ,
- \* 4. Completed application ,

## Application Situation

Ferry Pipe

## Application Method

The application was carried out in accordance with Belzona system leaflet VPF-11. This was followed by over-coating with Belzona 5821.

## Belzona Facts

The customer required a solution that was quick in order to get back into service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve