

Belzona Chocking Compound Stabilizes Lathe


ID: 7725

Industry: *Pulp & Paper*
Application: *GSS-Gaskets, Seals and Shims*
Substrate: *Concrete*
Products: ** Belzona 7111 (Industrial grade) ,*

Customer Location: *Poland*
Application Date: *March 2018*

Problem

Lathe in a paper factory required a solution to withstand compressive load of machinery and reduce vibrations.



Photograph Descriptions

- * The new lathe to be chocked. ,
- * The application is underway. ,
- * The completed solution. ,

Application Situation

Newly installed lathe at a paper manufacturer required a solid foundation.

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-13.

Belzona Facts

The Belzona solution secured the equipment for the long-term. Normally the machine would be bolted to the floor, which doesn't prevent corrosion or damage to the baseplate due to vibration.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

