

BELZONA PREVENTS WATER PENETRATION INTO A DATA STORAGE FACILITY

ID: 7786

Industry: Commercial Facilities

Customer Location: Virginia, USA

Application: FPA-Floor Problem Areas

Application Date: July 2004

Substrate: Concrete

Products: * Belzona 4111(Magma-Quartz) ,

Problem

Spider cracks compromising the integrity of the staircase and allowing water to penetrate into the building's data center underground.



Photograph Descriptions

* Showing Damage After powerwashing Completed application; the cracks filled, and the steps re-surfaced with Belzona 4111 for a long-term protection ,

Application Situation

Steps at the entrance to a financial building.

Application Method

The entire repair was complete on a Saturday afternoon after employees vacated the building. The cracks were filled with Belzona 4111 and the entire surface was restored for waterproofing and a long-lasting protection.

Belzona Facts

As an alternative, the Customer considered replacing the steps, or use other coatings. Belzona was chosen as it offered minimal downtime, durability and experience with similar situations.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are

manufactured under an ISO

9000 Registered Quality

Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024