

# Belzona Protects Washing Powder Hoppers

ID: 7800

## Industry:

Application: TCC-Tanks and Chemical Containment Areas

Substrate: Carbon steel

Products: \* Belzona 1331 ,

Customer Location: Czech Republic

Application Date: February 2017

## Problem

*The citric acid content of the washing powder was causing erosion-corrosion to the supply hoppers*



## Photograph Descriptions

- \* Application in progress, showing the unprotected substrate ,
- \* Closeup of the finished coating ,
- \* The equipment at hand ,

## Application Situation

Hoppers supplying storage bins in the manufacture of washing powder

## Application Method

The application was carried out in accordance with Belzona System Leaflet TCC-3. Belzona 1331 was applied by brush.

## Belzona Facts

A Belzona coating was chosen as the Customer sought after a long-term corrosion protection against citric acid, whilst also having the durability to withstand dry abrasion from powder.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve