

Belzona Rebuilds and Protects a Clarifier

ID: 7816

Industry: Water / Wastewater
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Concrete and Mild Steel
Products: * Belzona 4111 (Magma-Quartz),
* Belzona 5811 (Immersion Grade),
* Belzona 5111 (Ceramic Cladding),

Customer Location: France
Application Date: November 2018

Problem

The concrete roller track of this clarifier became damaged during operation and needed to be rebuilt. The floats and turbines had begun to corrode, so required protection from further deterioration.



Photograph Descriptions

- * Concrete repair on the roller track with Belzona 4111 and a former. ,
- * Protection of the tripods, turbines and floats with Belzona 5811. ,
- * Final application. ,
- * Close up view of final application. ,

Application Situation

Concrete roller track, metallic turbines and floats of a clarifier.

Application Method

The broken parts of concrete on the roller track were taken away and the surface of both the track and the clarifier trough were prepared by scarification. Metal components were prepared by grit blasting. After the surface preparation, the concrete was rebuilt using Belzona 4111 with a trowel and a former when needed, in accordance with a modified version of Belzona Know-How System Leaflet TCC-09. The trough next to the roller track was protected with Belzona 5111. The floats and turbines were protected with Belzona 5811.

Belzona Facts

The customer already contacted the distributor a few months ago to repair a roller track on another clarifier with Belzona 4111. 4

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

months later he realised that the repair was doing great and called the distributor for this much larger application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

