

Belzona Repair an Engine Casing of a Luxury Car


ID: 7882

Industry: General Industry
Application: ENC-Engines and Casings
Substrate: Cast Aluminium
Products: * Belzona 1212 ,

Customer Location: Azerbaijan
Application Date: October 2018

Problem

Several mounting bracket sets were cracked and broken. The customer wanted to achieve a perfect finish for both strength and aesthetic point of view. Belzona was chosen as an alternative to welding.



Photograph Descriptions

- * 1 - 3 Damaged engine mounting bracket sets ,
- * 4. Completed repair ,

Application Situation

The engine casing was damaged due to a car crash.

Application Method

The application was carried in accordance with modified versions of Belzona Know-How System Leaflets ENC-1 and ENC-2.

Belzona Facts

The car manufacturer would not supply only a new engine casing, the cost of the new engine was €95,000. The cost savings from repairing with Belzona was nearly 100% of the alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve