# BELZONA RESTORATION OF HISTORIC FEDERAL BUILDING

ID: 796

Industry: General Industry Customer Location: Pensacola, Florida
Application: RPA-Roof Problem Areas Application Date: September 2006

Substrate: Copper

Products: \* Belzona® 3111 (Flexible Membrane) fully reinforced system,

#### Problem

The copper gutters had to be maintained watertight without replacement.









## **Photograph Descriptions**

- \* Belzona® 3111 being applied,
- \* Belzona initially applied to gutter seams,
- \* View of the finished gutter system coated with Belzona® 3111,
- \* Another view of the finished gutter system coated with Belzona® 3111,

## **Application Situation**

Copper gutters of historic site. Gutter system is part of the original structure and it is not permitted by the Federal Government to change materials.

# **Application Method**

Application was carried out in accordance with Belzona System RPA-6. Power wire brushing and degreasing was carried out prior to application.

#### **Belzona Facts**

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

There was no way to replace the copper gutter system as dictated by the Federal Government. Alternatives such as silicone sealants would not provide required longevity. Belzona® 3111 was chosen due to the ability to coat the copper gutter system and maintain its functionality without removal. It maintained appearance to the satisfaction of the engineers.

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO ISO 14001:2015 EMS 695213

9000 Registered Quality Management System.

www.belzona.com

