

Belzona Protects Risers

ID: 8035

Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: Offshore gas production platform
Application Date: July 2016

Substrate: Carbon steel
Products: * Belzona 5831 (ST-Barrier),

Problem

Damage to coating protection led to severe corrosion.



Photograph Descriptions

- * 1. Severe corrosion ,
- * 2. Surface preparation ,
- * 3. Application in progress ,
- * 4. Finished application ,

Application Situation

Severe sorrosion on gas offshore platform risers

Application Method

Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21.

Belzona Facts

Belzona 5831 provides excelent adhesion on wet and minimal prepared surface and that fact makes this protection a very cost effective solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve