

# Belzona Protects Risers

ID: 8035

Industry: Oil & Gas  
Application: SOS-Ships and Offshore Structures

Customer Location: Offshore gas production platform  
Application Date: July 2016

Substrate: Carbon steel  
Products: \* Belzona 5831 (ST-Barrier),

## Problem

Damage to coating protection led to severe corrosion.



## Photograph Descriptions

- \* 1. Severe corrosion ,
- \* 2. Surface preparation ,
- \* 3. Application in progress ,
- \* 4. Finished application ,

## Application Situation

Severe sorrosion on gas offshore platform risers

## Application Method

Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21.

## Belzona Facts

Belzona 5831 provides excelent adhesion on wet and minimal prepared surface and that fact makes this protection a very cost effective solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve