

Belzona Repairs Conductor Casing On Offshore Platform

ID: 8045

Industry: Oil & Gas

Customer Location: Malaysia

Application:

Application Date: December 2018

Substrate: Wellhead conductor and casing - carbon steel

Products: * Belzona 7111 ,

* Belzona 3411 (Encapsulating Membrane) ,

Problem

The cavity between the well head and conductor casing corrodes, vibrates, and becomes misaligned. The engineers performed an analysis that showed very high concentrated stress levels and loads acting on the cavity.



Photograph Descriptions

- * Surface preparation by blasting ,
- * Pouring Belzona 7111 ,
- * Sealing with Belzona 3411 ,
- * Finished Application ,

Application Situation

Conductor casing on an offshore platform.

Application Method

Belzona 7111 was poured to fill the void and was then sealed with Belzona 3411.

Belzona Facts

Belzona 7111 has excellent flow characteristics which meant the void was easily filled. This saved the customer time and money as the application was completed in 1 day.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

