

Belzona helps in the protection of a surface under the granule scraper.

ID: 8060

Industry: General Industry

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona 4151 (Magma Quartz Resin) ,
* Belzona 5811 (Immersion Grade) ,

Customer Location: Puławy, Poland

Application Date: 2019

Problem

Corrosion of concrete and surface due to the scraper moving the granules around the area.



Photograph Descriptions

- * Application Area Picture ,
- * Area to be treated under the scraper ,
- * Applying Belzona 4151 & Belzona 5811 ,
- * Application Completed ,

Application Situation

Modernisation and protection of the surface area under the granule scraper.

Application Method

Repair any surface damaged concrete areas with Belzona 4151 Sealing the surface under the scraper using Belzona 5811.

Belzona Facts

Long-lasting chemical resistance with Belzona 5811 securing the surface under the scraper.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024

