

# Belzona secures a lifting winch

ID: 8075

Industry:

Application: SHM-Solids Handling Machinery

Customer Location: France

Application Date: August 2017

Substrate: Steel

Products: \* Belzona 7111 ,

## Problem

Chocking of heavy machinery winch.



## Photograph Descriptions

- \* Dredging vessel ,
- \* Area marked and dammed, ready for application ,
- \* Pouring in progress ,
- \* Completed application ,

## Application Situation

Lifting winch being secured on the deck of a dredging vessel

## Application Method

The installation was carried in accordance with Belzona System Leaflet GSS-12.

## Belzona Facts

The 4 supporting pads were chocked using Belzona 7111 in order to ensure optimum load transmission as well as long term

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2024

  
**BELZONA**  
Repair • Protect • Improve

protection against vibration. The fast curing properties of the material were a key factor for the operator of the ship.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

