

# Belzona secures a lifting winch

ID: 8075

Industry:

Application: *SHM-Solids Handling Machinery*

Customer Location: *France*

Application Date: *August 2017*

Substrate: *Steel*

Products: *\* Belzona 7111 ,*

## Problem

*Chocking of heavy machinery winch.*



## Photograph Descriptions

- \* Dredging vessel ,
- \* Area marked and dammed, ready for application ,
- \* Pouring in progress ,
- \* Completed application ,

## Application Situation

Lifting winch being secured on the deck of a dredging vessel

## Application Method

The installation was carried in accordance with Belzona System Leaflet GSS-12.

## Belzona Facts

The 4 supporting pads were chocked using Belzona 7111 in order to ensure optimum load transmission as well as long term

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

protection against vibration. The fast curing properties of the material were a key factor for the operator of the ship.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

