

Belzona secures a lifting winch

ID: 8075

Industry:

Application: SHM-Solids Handling Machinery

Customer Location: France

Application Date: August 2017

Substrate: Steel

Products: * Belzona 7111 ,

Problem

Chocking of heavy machinery winch.



Photograph Descriptions

- * Dredging vessel ,
- * Area marked and dammed, ready for application ,
- * Pouring in progress ,
- * Completed application ,

Application Situation

Lifting winch being secured on the deck of a dredging vessel

Application Method

The installation was carried in accordance with Belzona System Leaflet GSS-12.

Belzona Facts

The 4 supporting pads were chocked using Belzona 7111 in order to ensure optimum load transmsion as well as long term

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2025


BELZONA
Repair • Protect • Improve

protection against vibration. The fast curing properties of the material were a key factor for the operator of the ship.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



Copyright © Belzona International Limited 2025