

BELZONA REPAIRS GEAR BOX OF DREDGER

ID: 808

Industry: Marine
Application: ENC-Engines and Casings
Substrate: Cast Iron
Products: Belzona® 1111 (Super Metal)

Customer Location: Dredger, Egypt
Application Date: August 2006

Problem

Bearing housing of the gear box was badly worn due to bearing failure.



Photograph Descriptions

* View of the dredger cutter shaft gear box , * Worn out bearing housing , * Form was applied, then Belzona injected through the former , * Gear box bearing housing perfectly rebuilt ,

Application Situation

Gear Box of dredger cutter shaft.

Application Method

Application was carried out in accordance with modified version of Belzona Know-How System Leaflet ENC-3a.

Belzona Facts

Belzona successfully repaired the bearing housing insitu without machining which would have been difficult due to the large size of the gearbox.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve