

# Belzona 1812 in use at Peat Power Plant

ID: 8094

Industry: General Industry

Customer Location: Estonia

Application: SHM-Solids Handling Machinery

Application Date: 2018

Substrate: Stainless steel

Products: \* Belzona 1812 ,

## Problem

*It is very time consuming and costly for the client. Welding would make the pipe fragile and very difficult to use post-process.*



## Photograph Descriptions

- \* Screw before Belzona coating ,
- \* Screw complete with Belzona coating ,

## Application Situation

The customer's drawing shows that the screw tube must be welded with a hard facing CASTOLIN 5006. Screw was used for transporting peat.

## Application Method

Application was carried out in accordance with Belzona leaflet SHM-14. Grit blasting was used to prepare the surface, followed by a lining of Belzona 1812

## Belzona Facts

Little down time for the customer and saving them money contributed to winning the job. According to the customer feedback, the screws have been working for a year and there is no sign of wear.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve