BELZONA PROVIDES COST EFFECTIVE MAINTENANCE OF OIL CENTRIFUGES

ID: 81

Industry: Oil & Gas Customer Location: International Supplier of Oil Equipment

Application: TCC-Tanks and Chemical Containment Application Date: Ongoing since March, 1994

Areas

Substrate: Steel

Products: * Belzona® 1321 (Ceramic S-Metal),

Problem

The units revolve at 3500rpm. and the sand particles cause severe erosion requiring the units to be completely overhauled on an annual basis.







Photograph Descriptions

- * Centrifuge components being grit blasted. ,
- * Some of the components after coating with Belzona® 1321. ,
- * The scroll from a centrifuge.,

Application Situation

Centrifuges used to separate fine sand particles from oil production

Application Method

The application is carried out in accordance with Belzona Know-How Leaflet TCC-3.

Belzona Facts

Service life of Belzona® 1321 is 12-18 months at which point minor touch-up is required. The Belzona application is a third the cost of the previous annual overhaul at \$10,000.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve