

# Shopping centre step with Belzona grip system

ID: 8128

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Stone*  
Products: *\* Belzona 4411 Granogrip ,*  
*\* Belzona 9221 Surefoot white ,*

Customer Location: *Paisley, Scotland*  
Application Date: *October 2018*

## Problem

*Limited closure times were available, any solution had to be fast back to service.*



## Photograph Descriptions

- \* Close up of application ,
- \* Top down view ,
- \* Bottom view ,

## Application Situation

A set of stone steps leading to the entrance of a shopping centre was identified as a potential slip hazard in wet or icy conditions. A hard wearing, easy to see grip system was required to give positive traction to pedestrians using the steps.

## Application Method

The step nosings were abraded with a floor grinder. The Belzona 4411 system was then applied by brush before the Belzona 9221 was sprinkled on top to form the grip system

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

The application was able to be carried out over one day so minimal disruption to the area was caused

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

