

BELZONA UPGRADES SPIRITS CONTAINMENT AREA

ID: 8133

Industry: General Industry Customer Location: Distillery, Scotland

Application: TCC-Tanks and Chemical Containment Application Date: 2011

Areas

Substrate: Concrete

Products: * Belzona 4131 (Magma-Screed),

* Belzona 4141 (Magma-Build), * Belzona 5811 (Immersion Grade),


Problem

The existing protective system had failed. The chemical containment area could no longer be relied upon to prevent liquid loss into the groundwater/watercourse in the event of a spillage.









Photograph Descriptions

- * 1. Containment area prior to Belzona Application,
- * 2. Application of Belzona 5811 underway,
- * 3. Completed Application,
- * 4. Area revisited in 2019,

Application Situation

Spirit containment area/bund became damaged over time.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Belzona 4131 and Belzona 4141 were used to repair the degraded sections of the walls and to create fillets to all horizontal and vertical corners of the bund. The floor was screeded with Belzona 4131 at 6mm to provide maximum impact resistance. A two coat system of Belzona 5811 was then applied

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com



to all the internal surfaces of the bund.

Belzona Facts

The Belzona system provides excellent resistance to permeation. The reinforcement of wall and floor joints will ensure long term containment without cracking or breaks in the bund lining. The coating is a bit dirty (covered in whisky black fungus) but otherwise in perfect condition 8 years on!